






















Инструкция по установке



VN-59






NO.	Designation	Pieces	NO.	Designation	Pieces
1		X1	7	 $\varnothing 8$	X7
2		X1	8		X2
		X1	9		X2
		X1			X2
		X1			X1
		X1			X1
		X1			X1
3	 ST4X35	X7			X1
	 ST4X35	X7			X1
4		X11/X5/X8			X4
5	 ST4X10	X5			X2
6		X2			X2
					X1
					X1
					X2
					X2
					X1
					X4
					X2
					X1
			No handle		
			 $\varnothing 8$ $\varnothing 3.2$		


1.




2.




b
(E)




b
(F)








b
(G)





b
(H)














5.














6.












NO.	Designation	Pieces	NO.	Designation	Pieces
1		X1	7.1		X1
2		X1	7.2		X1
3	 $\phi 8$	X4	8	A 	X1
4	 $\phi 8$ ST4X35	X4		B 	X1
5		X5	 $\phi 8$ $\phi 3.2$		
6	 $\phi 8$ ST4X10	X5			



1.








2.








b
(8-A)



b
(8-B)





OR

